


# Product Safety Recall

Do you own this product?



## Makita 18V DGP180ZBK Grease Gun

- Automatic pressure switching function maintains steady flow rate regardless of pressure
- 1,200mm flexible hose length for access to hard to reach places
- Maximum 10,000psi discharge pressure and 295mL/min discharge rate
- Variable speed trigger for control over grease flow rate



**Date sold:** Since 25 February 2021 - 31 March 2025



**Why the product is recalled:** Hose Set 1200 (191W58-9) and Hose Set 600 (191W59-7) which are used with the 18V DGP180ZBK Grease Gun are non-compliant in accordance with ISO 1402.

**Hazard:** Repeatedly bending the tip of the hose to inject grease into narrow spaces can cause a hole to form near the tip of the hose, potentially leading to grease spraying out. It may cause serious personal injury to the operator if the correct protective equipment isn't used.



- Makita recommends customers immediately stop using the 18V DGP180ZBK Grease Gun.
- Remove any grease from the barrel and return the entire tool to your nearest Makita Factory Service Centre (FSC) for a replacement of the affected parts at no charge.



- Use the following link to find your nearest [Makita FSC - Factory Service Centres - Makita Australia](#).
- Contact our enquiries team on 1300 361 690 (8am-5pm AEST) for assistance in locating your nearest Makita FSC or if you have any further questions or concerns.



**Purchased from:** All Makita Australia Authorised Dealers.  
Please see the dealer list [here](#).

See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information